

To reset the tripmeter, press and hold the left control button for more than 2 seconds when the display is in the "TRIP 1" or "TRIP 2" mode.

