


NOTE:

- (1) If any sign of the above conditions is noticed, consult your HONDA dealer for further inspection.
- (2) The rear suspension units on the CB 500 are sealed at the factory and do not require servicing




① Grease nipple

NEVER attempt to destroy the seal and disassemble the rear suspension damper units.

2. Rear Fork Bushing Lubrication

There are two lubrication points ① and ② as shown in the figure. It is recom-



② Grease nipple