


To reset the tripmeter, push and hold the left control button when the display in the "TRIP 1" or "TRIP 2" mode.



(4) TRIP 1