

Radiator Servicing

The cooling system should be serviced at the maintenance intervals shown on page 110.

Recommended coolant:

Use only a high quality ethylene glycol base anti-freeze containing inhibitors for corrosion protection and specifically recommended for use in aluminum engines. The CX500TURBO cooling system has a 50/50 solution of anti-freeze and water from the factory.

Limpieza del radiador

El sistema de enfriamiento deberá limpiarse en los intervalos de mantenimiento indicados en la página 112.

Líquido de refrigeración recomendado:

Utilice sólo una solución anticongelante de base de etilenglicol de buena calidad que contiene inhibidores para la protección contra corrosión y las recomendadas específicamente para el uso para motores de aluminio. El sistema de enfriamiento del CX500TURBO tiene una solución 50/50 de anticongelante y agua, ya llenada en la fábrica.