


Indicators & Displays

Odometer

The odometer shows the total miles or kilometers ridden with the ODO display. The odometer locks at 999,999 when the readout exceeds 999,999.



Tripmeter

The tripmeter shows the number of miles or kilometers ridden with the TRIP display, since you last reset the tripmeter. The tripmeter returns to 0 when the readout exceeds 999.9.

To reset the tripmeter, press and hold the mode switch with the display in the tripmeter mode.

