


Gauges, Indicators & Displays

To reset the tripmeter, push and hold the button (1) for more than 2 seconds when the display in the tripmeter A or tripmeter B mode.



(1) odometer/tripmeter/digital clock
select and reset button