



PARTS CATALOGUE NEWS

Honda Motor Co., Ltd.
Customer Service Technology Development Division

PARTS CATALOGUE - CORRECTED

Printed in Japan

CODE NO.	15KVC703
PARTS CATALOGUE NEWS	GLH1251SH/GLH1252SH GLH1253SH/GLH125SH GLH1251SH7/8/A GLH1252SH7/8/A GLH1253SH8 GLH125SHC
NEWS NO.	004

(CH-KD)KVC

Block No.	Ref. No.	Note	Part No.	Description	Reqd. QTY				Serial No.	Parts catalogue code
					1/2SH 7	1/2/3SH 8	GLH125 A	1/2SH C		
F-2-1	7	A	37140-KVC-680	CASE COMP, UPPER	-	-	-	1	-----	2TU, 2U
		T	37140-KVX-601	-	-	-	1	-----	2AG, 2CL, 2LA, 2PE, 3AG, 3LA, 4AG, 4LA, AG, CL, LA, PE
F-3	5	T	35151-KVC-670	SWITCH COMP., STARTER	-	-	-	1	-----	2CL, CL
		A	35151-KVC-680	-	-	-	1	-----	2TU
	6	T	35201-KVC-670	SWITCH COMP., WINKER	-	-	-	1	-----	2CL, CL
		A	35201-KVC-680	-	-	-	1	-----	2TU
F-5-1	2	T	35010-KVC-650	KEY SET	-	-	-	1	-----	2CL, 2PE, CL, PE
		A	35010-KVC-680	-	-	-	1	-----	2TU
	4	T	35100-KPN-601	SWITCH ASSY., COMBINATION & LOCK	-	-	-	1	-----	2AG, 2LA, 3AG, 3LA, 4AG, 4LA, AG, LA
		A	35100-KVC-681	-	-	-	1	-----	2TU
		A	35100-KVC-691	-	-	-	1	-----	2U
		T	35100-KPN-A01	-	-	-	1	-----	2CL, 2PE, CL, PE
	20	T	91059-KY2-711	SCREW, TAPPING, 3X16	-	-	-	3	-----	2CL, 2PE, 2TU, 2U, CL, PE
		T	91059-MZ0-760	-	-	-	3	-----	2AG, 2LA, 3AG, 3LA, 4AG, 4LA, AG, LA

NOTE A:PART NO. CHANGE D:NEWLY PROVIDED E:PART NO. DELETION K:REQUIRED NO. CORRECTION L:APPLICATION SERIAL NO. CORRECTION
T:APPLICATION CORRECTION Z:REMARKS CHANGE