

2. Check that the fasteners for the shock absorber attachment points ( 2 ) are secure.
3. Check for oil leaks in the shock absorber. If any rear suspension components appear worn or damaged, see your Honda dealer for further inspection.