


WIRING DIAGRAM



COLOR COMB. GROUND/MARKING

B	BLACK	B	BROWN
O	ORANGE	D	DARK BLUE
Y	YELLOW	L	LIGHT GREEN
G	GREEN	P	PINK
R	RED	W	WHITE
N	GRAY	G	GRAY

CONNECTION TABLE

IGNITION SWITCH		DIMMER SWITCH		ENGINE STOP SWITCH		STARTER SWITCH	
IG	BAT	H	HL	E	IG	BAT	ST
ON	OFF	HI	LO	OFF	OFF	FREE	ST
ON	OFF	HI	LO	OFF	OFF	PUSH	ST
ON	OFF	HI	LO	OFF	OFF	COIL	ST
ON	OFF	HI	LO	OFF	OFF	COIL	ST
ON	OFF	HI	LO	OFF	OFF	COIL	ST

CONNECTION TABLE

LIGHTING SWITCH		LIGHTING ENGINE STOP SWITCH		LIGHTING STOP SWITCH		IGNITION STOP SWITCH	
LO	HI	LO	HI	LO	HI	LO	HI
ON	OFF	ON	OFF	ON	OFF	ON	OFF
ON	OFF	ON	OFF	ON	OFF	ON	OFF
ON	OFF	ON	OFF	ON	OFF	ON	OFF
ON	OFF	ON	OFF	ON	OFF	ON	OFF
ON	OFF	ON	OFF	ON	OFF	ON	OFF

CONNECTOR OF SWITCH