- 3. If the engine is cold, move the choke lever left to the full choke position (see Fig. 2-6).
- 4. Raise the decompression lever (Fig. 2-10), located on the right side of the engine, to the "Decomp" position (2).
- 5. Put your foot on the kick starter and depress the pedal from the top of the stroke all the way to the bottom with a rapid, continuous motion. The decompression lever will automatically return to the lowered position.




Fig. 2-10 (1) Decompression lever (2) "Decomp" position