

### Cleaning the battery terminals

Remove the battery (p. 66).

- Mild corrosion (white powder on the terminals):  
Wipe after applying warm water.
- Severe corrosion:  
Use sandpaper or a wire brush.

Coat the terminals lightly with grease and install the battery.

If the battery is to be replaced, replace with the maintenance free battery.

