

03/05/20 10:11:42 31KCY680_110

Suspension

4. Loosen the screw (5) on the air cleaner connecting tube clamp and remove the air cleaner connecting tube from the carburetor.

Be careful not to allow dust into the carburetor. Severe engine damage could result.

RIGHT SIDE

(5) screw
(8) subframe lower side bolt

5. Disconnect the electrical connectors (6).

(6) electrical connectors
(7) rubber band and clip
(9) subframe lower side bolt
(10) subframe upper bolt

(cont'd)

Service Your Honda 101