



Instruments *(Continued)*

Failure Information

Indication	Explanation	Remedy
	When your motorcycle has a problem with the PGM-FI system.	Reduce speed and have your motorcycle inspected by your dealer as soon as possible.
	CBR1000S1/S2 When your motorcycle has a problem with the ÖHLINS Smart EC system.	Reduce speed and have your motorcycle inspected by your dealer as soon as possible.