

Competition Inspection

No	Item	Inspect For:	Action	Refer to Page:
11	swingarm bearings	smooth operation	replace	80
12	rear suspension linkage bearings	smooth operation and secure installation	replace or tighten	80
13	brake pads	wear beyond service limit	replace	85
14	drive chain: max. length/pin	25.1 in (638 mm) / 41 pins	replace	100
15	sprockets	wear and secure installation	replace or tighten	101
16	seat	security	tighten	–
17	control cables	smooth operation, kinks and correct routing	lubricate or replace	–
18	engine mounting bolts	tightness	tighten	–