

# Specifications

| <b>Electrical</b> |                             |
|-------------------|-----------------------------|
| battery           | GYZ16H<br>12 V-16 Ah (10HR) |
| generator         | 0.45 kW/5,000 rpm           |

| <b>Lights</b>   |                  |
|---|------------------|
| headlight   | 12 V 35/35 W × 2 |
| brake/tail light  | LED              |
| neutral indicator                                       | LED              |
| reverse indicator                                       | LED              |
| high coolant temperature indicator                      | LED              |
| PGM-FI indicator  | LED              |
| PS (Electric Power Steering) indicator (TRX420FA2 only) | LED              |

| <b>Fuses</b>                                  |                |
|---|----------------|
| main 1  | 30 A           |
| main 2  | 10 A           |
| shift motor                                   | 30 A           |
| other   | 20 A × 2, 10 A |
| PS (Electric Power Steering) (TRX420FA2 only) | 40 A           |