


F-1V
HEADLIGHT (WITH VISOR)



Service Item	F.R.T.	BOM Of Group Number: F-1V Model :: Splendor (Dec, 1993)			
		Ref No.	Part Number	Description	Req.
HEADLIGHT ASSY.	0.1				
BULB, HEADLIGHT	--	19	83402-KCC-900	PANEL , INNER	1
DASH BULB	--	20	83407-KCC-902	CUSHION, FR. VISOR	2
SOCKET ASSY., HEAD LIGHT	0.2	21	90112-SB4-000	BOLT, FLANGE, 6 X 14	2
SOCKET ASSY., POSITION LIGHT	--	22	92000-08012-0A	BOLT, HEX. ,8 X 12	2
UNIT, HEADLIGHT	--	23	93500-04040-0H	SCREW, PAN, 4 X 40	1
(INC. RELATIVE PART)	--	24	93500-05010-1H	SCREW, PAN, 5 X 10	2
STAY HEADLIGHT BRACKET	--	25	94101-04800	WASHER ,PLAIN ,4MM	1
STAY R/L HEADLIGHT	--	26	94101-08000	WASHER, PLAIN, 8MM	2
VISOR FR.	--	27	94111-08000	WASHER, SPRING, 8MM	2
PANEL INNER	--	28	95701-06012-08	BOLT, FLANGE, 6 X 12	4
		29	96001-06016-07	BOLT, FLANGE, SH. 6 X 16	2