


F 4

E-9

Crankcase • Oil pump

Cartor moteur •
Pompe à huile

Kurbelgehäuse • Ölpumpe



Item d'entretien	T.D.R.	N° de réf.	N° de pièce	Description	N° de requis									N° de série	Code de zone
					1515CM				NH80M						
					DD	SD	SE	DE	DD	SD	DE				
		(9)	15100-GC7-731	ENS. POMPE A HUILE	-	1	-	-	-	-	-	1153605			
			15100-GC8-013	ENS. POMPE A HUILE	-	-	1	-	-	-	-	1058235	B,1L		
			15100-GC8-721	ENS. POMPE A HUILE	-	-	-	-	1	1	-		E,F,G,U		
			15100-GC7-013	ENS. POMPE A HUILE	1	-	-	-	-	-	-	1166352	CM		
					1	-	-	-	-	-	-	1400001	AR,GR,1K		
			15100-GC8-023	ENS. POMPE A HUILE	-	-	-	-	1	-	-	1058236	1K		
					-	-	-	-	1	-	-	1400001	B,1L		
		10	15525-GA7-000	TUYAU DE PASSAGE D'HUILE	1	1	1	1	1	1	1		1L		
		11	15532-GC8-000	ISOLANT DE POMPE A HUILE	1	-	-	-	-	-	-	1166351	AR,GR,1K		
					1	-	-	1	1	-	-		SW,1L		
					-	1	1	-	1	1	1		AR,B,CM,E,F,G		
													U		
			15532-KG8-000	ISOLANT DE POMPE A HUILE	1	-	-	-	-	-	-	1166352	AR,GR,1K		
					1	-	-	-	-	-	-	1400001	1K		
		12	16211-GC7-000	ISOLANT DE CARBURATEUR	1	1	1	1	-	-	-				
			16211-GC8-000	ISOLANT DE CARBURATEUR	-	-	-	-	1	1	1				
		13	17100-GC7-000	TUYAU COMP. ADMISSION	1	1	1	1	-	-	-				
			17100-GC8-000	TUYAU COMP. ADMISSION	-	-	-	-	1	1	1		B,CM,E,F,U,1L		
			17100-GC8-610	TUYAU COMP. ADMISSION	-	-	-	-	-	1	-		G		
		14	17104-GC7-000	APPUI DE TUYAU	1	1	1	1	1	1	1				
		15	17111-GC8-003	JOINT DE TUYAU D'ADMISSION	1	1	1	1	1	1	1				
		16	17112-GC8-000	JOINT SUPERIEUR DE TUYAU D'ADMISSION	1	1	1	1	1	1	1				
		17	32913-KG8-000	AGRAFE DE FIL	1	1	1	1	1	1	1				
		18	90084-GC2-710	BOULON D'UNE DIRECTION, 3X28	-	-	-	-	-	1	-		G		